2121 Highway 97 P.O. BOX 938 ELLENSBURG, WASHINGTON 98926 PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED

SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SOLD TO: SHIP TO: GRAHAM CONTRACTING LTD YAKIMA RIVER BRIDGES I 90 568 lst AVE 3 EB TEMP BRIDGE SEATTLE WA 98104 BACK ONTO EB BRIDGE FROM EB LANE 98844 VERIFY DESIGNATED WASHOUT TIME LOAD SIZE CY/M3 ORDERED ZONE DRIVER/TRUCK # COUNTER START TICKET # 13:41 328 3.00 175080 0.00 3.80 P.O. # LOAD# CY/M3 DEL BATCH # WATER TRIM SLUMP PLANT 06/26/2020 3200023428 3.00 NEMCA PL' 5_00 Excessive Water is Detrimental to Concrete Performance WARNING I HAVE READ AND H,O Added By Request/Authorized By IRRITATING TO THE SKIN AND EYES UNDERSTAND ALL Contains Portland Cement. Wear Rubber Boots GAL X WARNINGS, PROPERTY and Gloves. PROLONGED CONTACT MAY CAUSE DAMAGE RELEASE BURNS. Avoid Contact With Eyes and Prolonged NOTICE: MY SIGNATURE RELOW INDICATES THAT I HAVE INFORMATION AND READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE Contact With Skin. In Case of Contact With Skin or WARRANTY INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF Eyes, Flush Thoroughly With Water. If Irritation ON THE REVERSE SIDE OF Persists, Get Medical Attention. KEEP AWAY THIS TICKET. LOAD RECEIVED BY FROM CHILDREN QUANTITY CODE DESCRIPTION UNIT PRICE EXTENDED PRICE 1545 Full Depth 1 yel Returned CLASS M ENVIROMENTAL FEE Sta 67+73-67+78 1.00 SHORT LOAD SHORT LOAD UNDER 5 CY Sta 67+92-67+97 * Arrived 12 min Late RETURNED TO PLANT LEFT JOB FINISH UNLOADING TIME ALLOWED DELAY EXPLANATION/CYLINDER TEST TAKEN JOB NOT READY SLOW POUR OR PUMP TRUCK AHEAD ON JOB ACCIDENT CITATION CONTRACTOR BROKE DOWN LEFT PLANT ARRIVED JOB START UNLOADING ADDED WATER + helich 25061 Subportal: TOTAL ROUND TRIP TOTAL AT JOB UNLOADING TIME Tax: GRAND TOTAL DATCH DATA

BATCH DATA						*	15.	45
Date/Time 06/26/2020	13:41		cket 175080	Truc 158	r)c	MixCode 320	Custon	mer Name/Id 98844 M CONTRACTING LTD
terial	33D 1650 1280 705 30.00 36.00 64.00 2.50	Target 5,018 3,994 2,115 62.39 108.00 192.00 7.50	Actual 4,930 3,960 2,165 62.00 108.00 192.00 7.00	Unit lb lb lb gal os os	Vare -0.8 -0.9 2.4 -0.6 0.0 0.0 -6.7	5 12 4 19.14	Moist 1.40m 4.20m	Load

2121 Highway 97 PO BOX 938 ELLENSBURG, WASHINGTON 98926

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC. ALL TIME OVER THIS CHARGED!

READY MIXED CONCRETE CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA

SOLD TO:

GRAHAM CONTRACTING LTD 568 lst AVE S SEATTLE WA 98104

CRUSHED GRAVEL

WASHED

SAND & GRAVEL

98844

921

YAKIMA RIVER BRIDGES EB TEMP BRIDGE

BACK ONTO EB BRIDGE

FROM EB LANE

WERTEY DESIGNATED WASHOUT

THE PERSON NAMED IN	OTHER DESIGNATION OF THE PERSON OF THE PERSO					TICKET #
229	The second second				0	
200124	3,00	3.00		167	0.0000	175110
P.O. #	LOAD #	CY/M3 DEL	BATCH #	JEWATER TRIM	SLUMP	PLANT
			Maria de la compansión de			
9200023428		2 00			5 00	NRMCA PL
	PO. #	201	P.O. # LOAD # CY/M3 DEL.	P.O. # LOAD # CY/M3 DEL. BATCH #	P.O. # LOAD # CY/M3 DEL BATCH # LWATER TRIM	PO. # LOAD # CY/M3 DEL BATCH # LWATER TRIM SLUMP

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND UNDERSTAND ALL WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

UNIT PRICE

UUANTITT	CODE	DESCRIPTION	1.00
2.00	328	CLASS M	
3.00	4	ENVIROMENTAL TEE	

1545 Full Deoth Zyd Returned

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAKEN	
				1. JOB NOT READY 6. TRUCK BROKE DOWL 2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AHEAD ON JOB 8. CITATION	N
LEFT PLANT	ARRIVED JOB	START UNLOADING		CONTRACTOR BROKE DOWN OTHER ADDED WATER	
1	155%		2210 10		1
TOTAL ROUND TRIP	/ TOTAL AT JOB	UNLOADING TIME	CEM 03	Celviah	7
The same of	THE RESERVE				

Subtotal: Tax:

AND TOTAL

BATCH DATA						in		100
Date/Time 06/29/2020	19:35		cket 175110	Truc 167	rk.	MixCode 328		mer Name/Id 98844 I CONTRACTING LTD
Material PG SAND CEM03 WAT01 WRA MWRA MEAE90	35D 1650 1280 705 30.00 36.00 54.00 3.00	Target 5,018 3,994 2,115 621.39 108.00 192.00 9.00	Actual 4,980 4,020 2,130 62.00 108.00 192.00 8.00	Unit lb lb lb ggl os os	Var% -0.8 0.6 0.7 -0.6 0.0 0.0	19.43	Moist 1.40m 4.20m	Load